



TEXAS DEPARTMENT OF LICENSING AND REGULATION

Licensing Division

P.O. Box 12157 - Austin, Texas 78711 - (512) 463-6599 - (800) 803-9202

Fax (512) 475-2871 - Web site: www.tdlr.texas.gov - E-mail: csboiler@tdlr.texas.gov

Notice of Violation

HUNTSMAN CORPORATION
SHAW WINKLER RISK IMPROVEMENT MANAGER
8600 GOSLING RD
SPRING TX 773814845

Date: 09/24/2014
Location Huntsman Corporation "Dayton"
3892 US HWY 90
DAYTON, TX 77535-0006

Nature of Business: Chemical

Attention Management:

A recent inspection of the referenced location indicates repairs are necessary. The inspection listed was conducted for the purpose of determining compliance with the State of Texas.

The violations that we found are listed below. Please take the proper corrective action to remove or remedy all listed violations on or before the compliance dates. A certificate of inspection cannot be issued until corrective action is completed.

If you have questions concerning this, please call us at the number listed above. Please contact the inspector for re-inspection to verify that the attached violation(s) has been corrected so an operating certificate can be issued.

Sincerely,

Rob Troutt

<u>TX Identification #</u>	<u>Equipment</u>	<u>Violation Date</u>	<u>Comply By Date</u>	<u>Inspector</u>
TX127346	Cleaver Brooks / 1978 / ube	03/18/2014	04/18/2014	Stephen K Cave Sr

Condition:

Water level indicator installed and cut-out valves were found as the incorrect type.

Corrective Action:

The wrong type of sight glass has internal lateral structural supports (webs) in a transparent gage glass that obstruct the viewing of the level. Both cut-out valves are also the wrong type, and require OS&Y with chain operators for safe means operation. Mr. Wallace, Maintenance Manager, is having new sight glass and cut-out valves ordered, and will replace when received.