

(Example)
INSPECTION REPORT

The following report identifies violations with the Texas Accessibility Standards (TAS). All items noted as "Unacceptable" must be corrected to comply with the Architectural Barriers Act, Texas Government Code, Chapter 469.

RAS Name:		RAS #:	
Date of the Inspection:		EABPRJ #:	
Project Information			
Project Name:			
Facility Name:			
Project Address:		City:	
Detailed description of construction activities:			
Owner Information:			
Name:			
Address:			
City:		State:	Zip:

UNACCEPTABLE

****NOTE: A curb ramp is located within the access aisle of the van-accessible parking space on the north side of the building¹. This violates the following:**

²4.6.3 Parking Spaces

³Accessible parking spaces shall be at least 96" in (2440 mm) wide. Parking access aisles shall be part of an accessible route to the building or facility entrance and shall comply with 4.3. Two accessible parking spaces may share a common access aisle (see Fig. 9b). Parked vehicle overhangs shall not reduce the clear width of an accessible route. Parking spaces and access aisles shall be level with surface slopes not exceeding 1:50 (2%) in all directions.

UNACCEPTABLE

****NOTE: The running slope of new sidewalks that connect the portable classroom building to the main building is 1:8⁴. This violates the following:**

4.3.7 Slope

An accessible route with a running slope greater than 1:20 is a ramp and shall comply with 4.8. Nowhere shall the cross slope of an accessible route exceed 1:50.

¹ Actual location of the deficiency
² Actual TAS reference number
³ Actual TAS text
⁴ Actual nature of the deficiency

IMPORTANT INFORMATION

The inspection report must meet all the criteria established by III.(M)2