Posting Requirements

For elevators, the certificate must be posted inside the car, or outside the car in the elevator lobby within 10 feet of the call button. Alternately, the certificate can be displayed in another area that is open to the public, but a plaque or notice indicating the location of the certificate must be posted in the elevator car or lobby. The letters on the notice must be at least 18-point font size. The notice must also state that the elevator is regulated by the Texas Department of Licensing and Regulation and list the Department's phone number, 800-803-9202, along with the building management's phone number. For escalators, the Certificate of Compliance must be posted in the escalator box. For other related equipment such as chairlifts or platform lifts, the certificate must be posted on the box containing the control circuitry.

The certificate below is designed to be cut out and displayed in a 5" x 7" frame.

Building Physical Location:
500 E JOHN CARPENTER FREEWAY
IRVING TX 75062

SUSAN CARBONE
500 EAST 114 LLC
2001 BRYAN ST STE 1550
DALLAS TX 75201-3011

CERTIFICATE OF COMPLIANCE

For
Elevators, Escalators, and Related Equipment

Decal Number:
74028

Date of Inspection:
JUNE 18 2012

Next Inspection Due:
JUNE 18 2013

Building Number:	ELBI-6940
Building Name:	500 EAST JOHN CARPENTER FREEWAY BUILDING
Contact Person:	SUSAN CARBONE
Building Owner:	500 EAST 114 LLC
Equipment Description:	PASSENGER

Waivers / Delays: See Below **Inspector's License Number:** 392

For information on waivers, delays, or violations found see: Website: www.license.state.tx.us/ElevatorSearch/

To report violations or complaints: Phone: 1-800-803-9202 Website: www.license.state.tx.us/complaintsOnline/

THIS CERTIFICATE OF COMPLIANCE WAS ISSUED BY THE TEXAS DEPARTMENT OF LICENSING & REGULATION UNDER TEXAS HEALTH AND SAFETY CODE §754.016. THE ABOVE DESCRIBED EQUIPMENT HAS BEEN INSPECTED BY A CERTIFIED INSPECTOR AND FOUND TO BE IN COMPLIANCE EXCEPT FOR ANY DELAYS OR WAIVERS GRANTED BY THE EXECUTIVE DIRECTOR.

Date Signed: AUGUST 07 2012

William H. Kuntz
Executive Director