



TEXAS DEPARTMENT OF LICENSING & REGULATION

Regulatory Program Management Division • PO Box 12157 • Austin, Texas 78711 • (512) 463-6599

www.tdlr.texas.gov

Boiler Equipment Report of Inspection

PURSUANT TO CHAPTER 755, HEALTH AND SAFETY CODE, 16 TX ADMINISTRATIVE CODE, CHAPTER 65, AND OCCUPATIONS CODE CHAPTER 51

TX# *	* ☐ 1ST INSPECTION	☐ INTERNAL ☒ EXTERNAL	STATUS: * ☒ ACTIVE	☐ DISCONNECTED IN PLACE	☐ EXEMPT	☐ NEW
TX182909	☒ SUBSEQUENT	☐ NON-CERTIFICATE	☐ JUNKED	☐ DISPOSITION UNKNOWN		☐ 2ND HAND

IDENTIFIED BY: * ☒ DECAL ☐ STAMP ☐ TAG	VARIANCE: * ☐ YES ☒ NO	TEXAS SPECIAL: * ☐ YES ☒ NO
--	---	--

PHYSICAL ADDRESS (if the physical address has changed a first inspection is required)	OWNER ADDRESS	MAILING ADDRESS
--	---------------	-----------------

NAME *	NAME	NAME
--------	------	------

LyondellBasell Channelview South (CVO) S	LyondellBasell Channelview South (CVO) S	LyondellBasell Channelview South (CVO) S
--	--	--

(Address 1) *	(Address 1)	(Address 1)
---------------	-------------	-------------

2502 Sheldon Rd	2502 Sheldon Rd	2502 Sheldon Rd
-----------------	-----------------	-----------------

(City, State, Zip) *	(City, State, Zip)	(City, State, Zip)
----------------------	--------------------	--------------------

Channelview, TX 77530-2681	Channelview, TX 77530-2681	Channelview, TX 77530-2681
----------------------------	----------------------------	----------------------------

LOCATION PHONE:	OWNER PHONE: 281.862.5063	CONTACT NAME: Vince Wilkes
-----------------	---------------------------	----------------------------

OBJECT LOCATION: *	BUSINESS EMAIL: Charles.Dummer@Lyondellbasell.com	CONTACT PHONE: 281.452.8267
--------------------	---	-----------------------------

E-96861 - PO/SM 2	Nature of Business: Chemical	BUSINESS EMAIL: vince.wilkes@lyondellbasell.com
-------------------	------------------------------	---

MANUFACTURER *	NAT'L BOARD #	SERIAL NUMBER	MFGR MODEL #
----------------	---------------	---------------	--------------

Ohmstede	002602	758322	
----------	--------	--------	--

Boiler MAWP *	YEAR BUILT *	INTERVAL *	BLR TYPE *	BLR USE CLASS *	BLR USE *	HEATING SURFACE	CAP (GAL)	MIN SRV	MAX STEAM	ASME STAMP *
---------------	--------------	------------	------------	-----------------	-----------	-----------------	-----------	---------	-----------	--------------

90	2008	12	Process Steam Generator	Process Steam Generator	Steam Greater than 15 PSI	4296	1514	LB/HR	LB/HR	U
----	------	----	-------------------------	-------------------------	---------------------------	------	------	-------	-------	---

SAFETY RELIEF VALVE DATA				LOW WATER CUTOFF TYPE			FUEL *		BTU/HR INPUT	
--------------------------	--	--	--	-----------------------	--	--	--------	--	--------------	--

SET PRESSURE	TOTAL CAP. *	# OF SAFETIES	☐ PROBE TYPE ☒ FLOAT & CHAMBER			Recovered Heat		BTU/HR OUTPUT		
--------------	--------------	---------------	---	--	--	----------------	--	---------------	--	--

HIGHEST * 90	15770	1	☐ FLOW SWITCH ☐ OTHER							
--------------	-------	---	---	--	--	--	--	--	--	--

LOWEST * 90	☐ BTU/HR ☒ #/HR	MAWP: 180								
-------------	--	-----------	--	--	--	--	--	--	--	--

EXPANSION TANK ASME * ☐ YES ☐ NO ☒ N/A			EXPANSION TANK MAWP			EXTERNAL PIPE ASME ☒ YES ☐ NO ☐ N/A				
--	--	--	---------------------	--	--	---	--	--	--	--

EXTENSION INSPECTION? ☒ YES ☐ NO			EXTENSION APPROVAL DATE (IF APPLICABLE) 02/02/2021							
---	--	--	--	--	--	--	--	--	--	--

Comments: In accordance with Texas Boiler Law and Rules, including §65.64(a)(1) which requires a request for extension to be submitted to TDLR not less than 30 days prior to the expiration date of the current certificate, location has certified that: 1. continuous water treatment under competent and experienced supervision since last internal inspection; 2. accurate and complete records of boiler water samples taken at intervals not exceeding 24 hours of operation; 3. accurate and complete records of dates and reasons object has been out of service, the nature of (continued on Supplemental Report...)										
---	--	--	--	--	--	--	--	--	--	--

--	--	--	--	--	--	--	--	--	--	--

--	--	--	--	--	--	--	--	--	--	--

--	--	--	--	--	--	--	--	--	--	--

--	--	--	--	--	--	--	--	--	--	--

--	--	--	--	--	--	--	--	--	--	--

--	--	--	--	--	--	--	--	--	--	--

--	--	--	--	--	--	--	--	--	--	--

--	--	--	--	--	--	--	--	--	--	--

--	--	--	--	--	--	--	--	--	--	--

--	--	--	--	--	--	--	--	--	--	--

--	--	--	--	--	--	--	--	--	--	--

--	--	--	--	--	--	--	--	--	--	--

--	--	--	--	--	--	--	--	--	--	--

--	--	--	--	--	--	--	--	--	--	--

--	--	--	--	--	--	--	--	--	--	--

--	--	--	--	--	--	--	--	--	--	--

--	--	--	--	--	--	--	--	--	--	--

--	--	--	--	--	--	--	--	--	--	--

I HEREBY CERTIFY THAT THIS IS A TRUE REPORT AS A RESULT OF MY INSPECTION.

Salvador S. Guzman

1852

SIGNATURE OF INSPECTOR

TX COMMISSION #

INSPECTION ORG.

Salvador Guzman

Mr. Vince Wilkes

02/19/2021

SIGNATURE OF INDIVIDUAL PRESENT AT INSPECTION*

DATE (MM/DD/YY) *

IS CONDITION OF OBJECT SUCH THAT A CERTIFICATE MAY BE ISSUED? *	☒ YES ☐ NO	(IF NO, EXPLAIN FULLY UNDER VIOLATIONS)
---	---	---



TEXAS DEPARTMENT OF LICENSING AND REGULATION

Licensing Division
(512) 463-6599 - (800) 803-9202
Fax (512) 475-2871 CSBoiler@TDLR.Texas.gov

Technical
(512) 539-5716
Boilers@TDLR.Texas.gov

P.O. Box 12157 - Austin, Texas 78711 - www.tdlr.texas.gov

Boiler Equipment Report of Inspection - Supplemental Report

TX # TX182909

Date: 02/19/2021

Location Name LyondellBasell Channelview South (CVO) S


Object Address 2502 Sheldon Rd, Channelview, TX 77530-2681

Location On Site E-96861 - PO/SM 2

Comments:

In accordance with Texas Boiler Law and Rules, including §65.64(a)(1) which requires a request for extension to be submitted to TDLR not less than 30 days prior to the expiration date of the current certificate, location has certified that: 1. continuous water treatment under competent and experienced supervision since last internal inspection; 2. accurate and complete records of boiler water samples taken at intervals not exceeding 24 hours of operation; 3. accurate and complete records of dates and reasons object has been out of service, the nature of all repairs, and the reason for those repairs as documented; and 4. for gas fired boilers the gas pressure regulation or reducing valve servicing the boiler is vented to a safe point of discharge.

Remarks:

Name of Authorized/Deputy Inspector Salvador Guzman Signature 

Inspection Organization TX COMMISSION # 1852 Date 02/19/2021

Owner/Operator LyondellBasell Channelview South (CVO) S Title POSM 11 Inspector

Name