



TEXAS DEPARTMENT OF LICENSING & REGULATION

Regulatory Program Management Division • PO Box 12157 • Austin, Texas 78711 • (512) 463-6599

www.tdlr.texas.gov

Boiler Equipment Report of Inspection

PURSUANT TO CHAPTER 755, HEALTH AND SAFETY CODE, 16 TX ADMINISTRATIVE CODE, CHAPTER 65, AND OCCUPATIONS CODE CHAPTER 51

TX# * TX104754	* <input type="checkbox"/> 1ST INSPECTION <input checked="" type="checkbox"/> SUBSEQUENT	<input type="checkbox"/> INTERNAL <input checked="" type="checkbox"/> NON-CERTIFICATE	<input checked="" type="checkbox"/> EXTERNAL	STATUS: * <input checked="" type="checkbox"/> ACTIVE <input type="checkbox"/> JUNKED	<input type="checkbox"/> DISCONNECTED IN PLACE	<input type="checkbox"/> EXEMPT	<input checked="" type="checkbox"/> NEW <input type="checkbox"/> 2ND HAND
-------------------	---	--	--	---	--	---------------------------------	--

IDENTIFIED BY: * <input type="checkbox"/> DECAL <input checked="" type="checkbox"/> STAMP <input type="checkbox"/> TAG	VARIANCE: * <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	TEXAS SPECIAL: * <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
--	---	--

PHYSICAL ADDRESS <small>(if the physical address has changed a first inspection is required)</small>	OWNER ADDRESS	MAILING ADDRESS
---	---------------	-----------------

NAME * Georgia Pacific	NAME Georgia Pacific	NAME Georgia Pacific
----------------------------------	--------------------------------	--------------------------------

(Address 1) * 20125 E 942	(Address 1) 20125 E 942	(Address 1) 20125 E. FM 942
-------------------------------------	-----------------------------------	---------------------------------------

(City, State, Zip) * Camden, TX 75934	(City, State, Zip) Camden, TX 75934	(City, State, Zip) Camden, TX 75934
---	---	---

LOCATION PHONE:	OWNER PHONE:	CONTACT NAME: Joe Gonzalez
-----------------	--------------	-----------------------------------

OBJECT LOCATION: * Boiler #3 (North Boiler)	BUSINESS EMAIL:	CONTACT PHONE: (936) 398-7350
---	-----------------	--------------------------------------

MANUFACTURER * ZURN INC	NATL BOARD # 018837	SERIAL NUMBER 99575	MFGR MODEL #
-----------------------------------	-------------------------------	-------------------------------	--------------

Boiler MAWP *	YEAR BUILT *	INTERVAL *	BLR TYPE *	BLR USE CLASS *	BLR USE *	HEATING SURFACE	CAP (GAL)	MIN SRV	MAX STEAM	ASME STAMP *
650	1977	12	Water Tube	Power Boiler	Steam Greater than 15 PSI	22037			160000-LB/HR	S

SAFETY RELIEF VALVE DATA			LOW WATER CUTOFF TYPE		FUEL *	BTU/HR INPUT
SET PRESSURE HIGHEST * 639	TOTAL CAP. * 162249	# OF SAFETIES 2	<input type="checkbox"/> PROBE TYPE	<input type="checkbox"/> FLOAT & CHAMBER	Wood	BTU/HR OUTPUT
LOWEST * 620	<input type="checkbox"/> BTU/HR	<input checked="" type="checkbox"/> #/HR	<input type="checkbox"/> FLOW SWITCH	<input checked="" type="checkbox"/> OTHER Transmitter		
EXPANSION TANK ASME * <input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> N/A			EXPANSION TANK MAWP		EXTERNAL PIPE ASME <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/> N/A	

EXTENSION INSPECTION? <input type="checkbox"/> YES <input type="checkbox"/> NO	EXTENSION APPROVAL DATE (IF APPLICABLE)
--	---

Comments: The Zurn steam boiler was inspected externally, while in service. The operating certificate was posted accordingly in the boiler room. No noticeable rusting or abnormalities were noted on any of the boiler's external piping. There is one steam valve outside of the steam drum that has a minor steam leak. This will be repaired during the next shut down in November. All the pressure and temperature gages were working properly. The low water cut offs were examined and were found to be functioning normally. The high limit switch was also examined and wa (continued on Supplemental Report...)

ITEM # - LAW/RULE	VIOLATION (ATTACH ADDITIONAL PAGES IF NECESSARY)

I HEREBY CERTIFY THAT THIS IS A TRUE REPORT AS A RESULT OF MY INSPECTION.

 SIGNATURE OF INSPECTOR Donald (DJ) Wallace	2013 TX COMMISSION #	XL Insurance America, Inc. INSPECTION ORG.
---	-------------------------	---

Joe Gonzales SIGNATURE OF INDIVIDUAL PRESENT AT INSPECTION *	09/10/2020 DATE (MM/DD/YY) *
---	---------------------------------

IS CONDITION OF OBJECT SUCH THAT A CERTIFICATE MAY BE ISSUED? * YES NO (IF NO, EXPLAIN FULLY UNDER VIOLATIONS)



TEXAS DEPARTMENT OF LICENSING AND REGULATION

Licensing Division
(512) 463-6599 - (800) 803-9202
Fax (512) 475-2871 CSBoiler@TDLR.Texas.gov

Technical
(512) 539-5716
Boilers@TDLR.Texas.gov

P.O. Box 12157 - Austin, Texas 78711 - www.tdlr.texas.gov

Boiler Equipment Report of Inspection - Supplemental Report

TX # TX104754

Date: 09/10/2020

Location Name Georgia Pacific


Object Address 20125 E 942, Camden, TX 75934

Location On Site Boiler #3 (North Boiler)

Comments:

The Zurn steam boiler was inspected externally, while in service. The operating certificate was posted accordingly in the boiler room. No noticeable rusting or abnormalities were noted on any of the boiler's external piping. There is one steam valve outside of the steam drum that has a minor steam leak. This will be repaired during the next shut down in November. All the pressure and temperature gages were working properly. The low water cut offs were examined and were found to be functioning normally. The high limit switch was also examined and was found to be working properly. PM logs, as well as water chemistry logs were reviewed and all is in good order. The safety relief valves were within the appropriate MAWP and BTU limits stamped on the boiler's data plate. The relief valves were all replaced last year and are tested annually.

Remarks:

Name of Authorized/Deputy Inspector Donald (DJ) Wallace Signature 

Inspection Organization XL Insurance America, Inc. TX COMMISSION # 2013 Date 09/10/2020

Owner/Operator Georgia Pacific Title _____
Name