



TEXAS DEPARTMENT OF LICENSING & REGULATION

Regulatory Program Management Division • PO Box 12157 • Austin, Texas 78711 • (512) 463-6599

www.tdlr.texas.gov

Boiler Equipment Report of Inspection

PURSUANT TO CHAPTER 755, HEALTH AND SAFETY CODE, 16 TX ADMINISTRATIVE CODE, CHAPTER 65, AND OCCUPATIONS CODE CHAPTER 51

TX# * TX236913	* <input type="checkbox"/> 1ST INSPECTION <input checked="" type="checkbox"/> SUBSEQUENT	<input type="checkbox"/> INTERNAL <input checked="" type="checkbox"/> NON-CERTIFICATE	<input checked="" type="checkbox"/> EXTERNAL <input type="checkbox"/>	STATUS: * <input checked="" type="checkbox"/> ACTIVE <input type="checkbox"/> JUNKED	<input type="checkbox"/> DISCONNECTED IN PLACE <input type="checkbox"/> DISPOSITION UNKNOWN	<input type="checkbox"/> EXEMPT <input type="checkbox"/>	<input checked="" type="checkbox"/> NEW <input type="checkbox"/> 2ND HAND
-------------------	---	--	--	---	--	---	--

IDENTIFIED BY: * <input checked="" type="checkbox"/> DECAL <input type="checkbox"/> STAMP <input type="checkbox"/> TAG	VARIANCE: * <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	TEXAS SPECIAL: * <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
--	---	--

PHYSICAL ADDRESS <small>(if the physical address has changed a first inspection is required)</small>	OWNER ADDRESS	MAILING ADDRESS
---	---------------	-----------------

NAME * Sanderson Farms - Waco - Processing Plant	NAME Sanderson Farms - Waco - Processing Plant	NAME Sanderson Farms
--	--	--------------------------------

(Address 1) * 301 Aviation Parkway	(Address 1) 301 Aviation Parkway	(Address 1) 301 Aviation Parkway
--	--	--

(City, State, Zip) * Waco, TX 76705-5468	(City, State, Zip) Waco, TX 76705-5468	(City, State, Zip) Waco, TX 76705-5468
--	--	--

LOCATION PHONE: 254.412.3800	OWNER PHONE:	CONTACT NAME: Ron Snyder
-------------------------------------	--------------	---------------------------------

OBJECT LOCATION: * Boiler Room, Blr. #1	BUSINESS EMAIL:	CONTACT PHONE: 254.412.3800 ext. 5610
---	-----------------	--

Nature of Business: Food		BUSINESS EMAIL: rsnyder@sandersonfarms.com
---------------------------------	--	---

MANUFACTURER * Cleaver Brooks	NATL BOARD # 14557	SERIAL NUMBER 0L105750	MFR MODEL # CB 200 500 150
---	------------------------------	----------------------------------	--------------------------------------

Boiler MAWP *	YEAR BUILT *	INTERVAL *	BLR TYPE *	BLR USE CLASS *	BLR USE *	HEATING SURFACE	CAP (GAL)	MIN SRV	MAX STEAM	ASME STAMP *
150	2007	12	Fire Tube	Power Boiler	Steam Greater than 15 PSI	2500		17250-LB/HR	17250-LB/HR	S

SAFETY RELIEF VALVE DATA			LOW WATER CUTOFF TYPE		FUEL *	BTU/HR INPUT
SET PRESSURE HIGHEST * 150	TOTAL CAP. * 21632	# OF SAFETIES 2	<input type="checkbox"/> PROBE TYPE	<input checked="" type="checkbox"/> FLOAT & CHAMBER	Natural Gas	20412000
LOWEST * 150	<input type="checkbox"/> BTU/HR	<input checked="" type="checkbox"/> #/HR	<input type="checkbox"/> FLOW SWITCH	<input type="checkbox"/> OTHER _____		BTU/HR OUTPUT
EXPANSION TANK ASME * <input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> N/A			EXPANSION TANK MAWP 150		EXTERNAL PIPE ASME <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/> N/A	

EXTENSION INSPECTION? <input type="checkbox"/> YES <input type="checkbox"/> NO	EXTENSION APPROVAL DATE (IF APPLICABLE)
--	---

Comments: The Cleaver Brooks steam boiler was inspected externally, while in service. The operating certificate was posted accordingly in the boiler room. No noticeable rusting or abnormalities were noted on any of the boiler's external piping. All the pressure and temperature gages were working properly. The low water cut offs were examined and tested, and were found to be functioning normally. The high limit switch was also examined and tested, and was found to be working properly. The flame detector was tested and was also working properly. The safety r (continued on Supplemental Report...)

ITEM # - LAW/RULE	VIOLATION (ATTACH ADDITIONAL PAGES IF NECESSARY)

I HEREBY CERTIFY THAT THIS IS A TRUE REPORT AS A RESULT OF MY INSPECTION.

	2013	XL Insurance America, Inc.
SIGNATURE OF INSPECTOR Donald (DJ) Wallace	TX COMMISSION #	INSPECTION ORG.

Ron Snyder	05/31/2022
SIGNATURE OF INDIVIDUAL PRESENT AT INSPECTION *	DATE (MM/DD/YY) *

IS CONDITION OF OBJECT SUCH THAT A CERTIFICATE MAY BE ISSUED? * YES NO (IF NO, EXPLAIN FULLY UNDER VIOLATIONS)



TEXAS DEPARTMENT OF LICENSING AND REGULATION

Licensing Division
(512) 463-6599 - (800) 803-9202
Fax (512) 475-2871 CSBoiler@TDLR.Texas.gov

Technical
(512) 539-5716
Boilers@TDLR.Texas.gov

P.O. Box 12157 - Austin, Texas 78711 - www.tdlr.texas.gov

Boiler Equipment Report of Inspection - Supplemental Report

TX # TX236913

Date: 05/31/2022

Location Name Sanderson Farms - Waco - Processing Plant


Object Address 301 Aviation Parkway, Waco, TX 76705-5468

Location On Site Boiler Room, Blr. #1

Comments:

The Cleaver Brooks steam boiler was inspected externally, while in service. The operating certificate was posted accordingly in the boiler room. No noticeable rusting or abnormalities were noted on any of the boiler's external piping. All the pressure and temperature gages were working properly. The low water cut offs were examined and tested, and were found to be functioning normally. The high limit switch was also examined and tested, and was found to be working properly. The flame detector was tested and was also working properly. The safety relief valves were within the appropriate MAWP and BTU limits stamped on the boiler's data plate. The relief valves were all replaced during the internal inspection.

Remarks:

Name of Authorized/Deputy Inspector Donald (DJ) Wallace Signature 

Inspection Organization XL Insurance America, Inc. TX COMMISSION # 2013 Date 05/31/2022

Owner/Operator Sanderson Farms - Waco - Processing Plant Title _____
Name