



# TEXAS DEPARTMENT OF LICENSING AND REGULATION

*Licensing Division*

*P.O. Box 12157 - Austin, Texas 78711-2157 - (512) 463-6599 - (800) 803-9202 - fax (512) 475-2871*

*Web site: [www.license.state.tx.us](http://www.license.state.tx.us)*

SEPTEMBER 16 2011

DAVE HAVEL  
BORDEN MILK PRODUCTS  
5327 S LAMAR ST  
DALLAS TX 75215-4924

ELBI Number: 19814  
Inspection Date: 05/05/11

Decal Number: 56452

Re: Request For Information for Certificate of Compliance for an Elevator, Escalator, or Related Equipment for BORDEN MILK PRODUCTS

The Department received the Report of Inspection referenced above on SEPTEMBER 08 2011. However, the report is incomplete.

The following information is required to continue processing the report:

- \* The payment submitted was insufficient. The fee to process a report of inspection and receive a certificate of compliance is \$20. The report must be submitted within 90 days of the date of inspection. The late fee(s) are \$10 for every 30 day period that the report of inspection is late. The amount required to continue processing your report is \$ 10.00.
- \* Please have the owner or owner's agent sign the report of inspection form.

You must return a copy of this letter with the Report of Inspection completed with all required information and attachments by OCTOBER 16 2011.

Failure to resolve this matter may result in this case being forwarded to the Enforcement Division of TDLR, where administrative penalties of up to \$5000 per violation, per day, may be assessed. If you have questions, please contact the Department by email at [customer.service@license.state.tx.us](mailto:customer.service@license.state.tx.us) or by phone at 512-463-6599 or 800-803-9202.

Thank you,

Licensing Division

---

*Frank S. Denton, Chair - Conroe, Texas*

*LuAnn Morgan - Midland, Texas*  
*Mike Arismendez - Shallowater, Texas*

*Fred Moses - Plano, Texas*  
*Lilian Norman-Keeney - Taylor Lake Village, Texas*

*Lewis Benavides - Oak Point, Texas*  
*Debrah A. Yuro - Austin, Texas*