



TEXAS DEPARTMENT OF LICENSING AND REGULATION

Licensing Division

P.O. Box 12157 - Austin, Texas 78711-2157 - (512) 463-6599 - (800) 803-9202 - fax (512) 475-2871

Web site: www.license.state.tx.us

MAY 29 2013

JOHN HUNTER, ENGINEERING
WESTIN HOTEL DFW AIRPORT
4545 W JOHN CARPENTER FWY
IRVING TX 75063-2302

ELBI Number: 3332
Inspection Date: 05/09/13

Decal Number: 3371

Re: Request For Information for Certificate of Compliance for an Elevator, Escalator, or Related Equipment for WESTIN HOTEL DFW AIRPORT

The Department received the Report of Inspection referenced above on MAY 24 2013. However, the report is incomplete.

The following information is required to continue processing the report:

* Please provide building owner name, address and phone number.

You must return a copy of this letter with the Report of Inspection completed with all required information and attachments by JUNE 28 2013.

Failure to resolve this matter may result in this case being forwarded to the Enforcement Division of TDLR, where administrative penalties of up to \$5000 per violation, per day, may be assessed. If you have questions, please contact the Department by email at customer.service@license.state.tx.us or by phone at 512-463-6599 or 800-803-9202.

Thank you,

Licensing Division

Frank S. Denton, Chair - Conroe, Texas

LuAnn Morgan - Midland, Texas
Mike Arismendez - Shallowater, Texas

Fred Moses - Plano, Texas
Lilian Norman-Keeney - Taylor Lake Village, Texas

Ravi Shah - Carrollton, Texas
Deborah A. Yurco - Austin, Texas