

REGISTERED ACCESSIBILITY SPECIALIST BULLETIN

2012



TAS

Texas Department of Licensing and Regulation • Compliance Division • Architectural Barriers

Effective Date: May 15, 2017

RAS 2017-02

Architectural Barriers

Rule: 68.75(b) – Responsibilities of the Registered Accessibility Specialist

TDLR has added Architectural Barriers Rule 68.75(b) allowing RAS to ‘share services’. While RAS may share services, each RAS remains accountable for his or her individual work product and must adhere to all laws, rules, and procedures. The RAS Procedures (effective April 2007) were not updated or modified, therefore Project Status Update (PSU) forms and files remain the responsibility of each individual RAS. See RAS Bulletins 2015-02 and 2015-03 for clarification regarding transfers and requests for inspection.