

1994 Texas Accessibility Standards
Technical Memorandum

**Texas Department of Licensing and Regulation
Architectural Barriers**

Issue Date: January 5, 1999

TM 99-03

**Drive-up Automatic Teller Machines
4.1.3(20) Exception**

TAS 4.1.3(20) includes the exception that drive-up only automatic teller machines are not required to comply with TAS 4.27.2 and 4.27.3. That exception should refer to TAS 4.34.2 and TAS 4.34.3.

Additionally, drive-up only automatic teller machines are not required to comply with the accessible route requirement noted in 4.34.1.

Applicable to 1994 TAS Only