



TEXAS DEPARTMENT OF LICENSING AND REGULATION

Licensing Division

P.O. Box 12157 - Austin, Texas 78711-2157 - (512) 463-6599 - (800) 803-9202 - fax (512) 475-2871

Web site: www.license.state.tx.us

SEPTEMBER 13 2011

BOB JOHNS
SEARS HOLDINGS COMPANY
13131 PRESTON RD
DALLAS TX 75240-5203

ELBI Number: 13674
Inspection Date: 06/20/11

Decal Number: 43547

Re: Request For Information for Certificate of Compliance for an Elevator, Escalator, or Related Equipment for SEARS & ROEBUCK COMPANY

The Department received the Report of Inspection referenced above on SEPTEMBER 02 2011. However, the report is incomplete.

The following information is required to continue processing the report:

- * Your report of inspection indicates that violation(s) were found during the inspection. You must either attach a violation status letter indicating that all violations are corrected or are under contract to be corrected or attach a Delay/Waiver Form with appropriate fees for each violation listed. You may have attached a violation status letter or a Delay/Waiver Form for one or more of the violations, but you did not attach documentation for all. You can view and print a Delay/Waiver Form on the Department's website at <http://www.license.state.tx.us>.

You must return a copy of this letter with the Report of Inspection completed with all required information and attachments by OCTOBER 13 2011.

Failure to resolve this matter may result in this case being forwarded to the Enforcement Division of TDLR, where administrative penalties of up to \$5000 per violation, per day, may be assessed. If you have questions, please contact the Department by email at customer.service@license.state.tx.us or by phone at 512-463-6599 or 800-803-9202.

Thank you,

Licensing Division

Frank S. Denton, Chair - Conroe, Texas

LuAnn Morgan - Midland, Texas
Mike Arismendez - Shallowater, Texas

Fred Moses - Plano, Texas
Lilian Norman-Keeney - Taylor Lake Village, Texas

Lewis Benavides - Oak Point, Texas
Debrah A. Yuro - Austin, Texas