



ELBI Number: 3332

Texas Department of Licensing and Regulation

Licensing Division

P.O. Box 12157 - Austin, Texas 78711-2157 - (512) 463-6599 - (800) 803-9202 - fax (512) 475-2871

Web site: www.tdlr.texas.gov

DECEMBER 07 2021

**DONOVAN WADDING
FACILITIES MANAGER
4545 W JOHN CARPENTER FWY
IRVING TX 75063-2302**

ELBI Number: 3332
Equipment Number: 98278

Date of Inspection: 08/20/21

Re: Request For Information for Certificate of Compliance for an Elevator, Escalator, or Related Equipment for THE WESTON DALLAS DFW AIRPORT

The Department received the Elevator Equipment Report of Inspection referenced above on DECEMBER 07 2021. However, the report is incomplete.

The following information is required to continue processing the report:

- * Your payment was insufficient. The fee to process an inspection report and receive a certificate of compliance is \$20. If the report is not submitted within 60 days of the date of inspection, late fees will be charged. Late fees are \$10 for every 30-day period after the 60 days. The amount required to continue processing your report is
\$ 40.00.
- * Please provide building owner name, address and phone number.

You must return a copy of this letter with any requested information. You can submit required attachments via TDLR webform at <https://www.tdlr.texas.gov/help>. You may also contact Customer Service for assistance at 512-463-6599 or 800-803-9202.

Thank you,

Licensing Division