

1994 Texas Accessibility Standards  
*Technical Memorandum*

---

**Texas Department of Licensing and Regulation  
Architectural Barriers**

Issue Date: January 25, 2000

TM 00-01

---

**Self-Service Gasoline Pumps**

**Scoping and Application  
4.1.3(13), 4.2, 4.27**

In March 1998, TDLR agreed to suspend enforcement of TAS 4.26, TAS 4.1.3 and TAS 4.27 relating to fuel dispensers.

This agreement to abate enforcement at fuel dispensers was premised on industry's representation that technology had not been fully developed in order to comply with the applicable sections of the Texas Accessibility Standards.

Because there are now industry-wide alternative methods for complying with TAS, and pursuant to our prior agreements, TDLR will immediately begin to enforce the TAS requirements on control mechanisms for fuel pumps as they relate to credit card readers.

Effective December 1, 1999, the suspension of enforcement is no longer valid. TDLR is now requiring 100% of all fuel dispensers installed at facilities constructed or renovated after December 1, 1999 to comply with TAS 4.2 and 4.27. References to "constructed or renovated" mean the beginning date of construction or renovations.