



TEXAS DEPARTMENT OF LICENSING & REGULATION

Regulatory Program Management Division • PO Box 12157 • Austin, Texas 78711 • (512) 463-6599

www.tdlr.texas.gov

Boiler Equipment Report of Inspection

PURSUANT TO CHAPTER 755, HEALTH AND SAFETY CODE, 16 TX ADMINISTRATIVE CODE, CHAPTER 65, AND OCCUPATIONS CODE CHAPTER 51

TX# * TX239271	* <input type="checkbox"/> 1ST INSPECTION <input checked="" type="checkbox"/> SUBSEQUENT	<input checked="" type="checkbox"/> INTERNAL <input type="checkbox"/> EXTERNAL <input type="checkbox"/> NON-CERTIFICATE	STATUS: * <input checked="" type="checkbox"/> ACTIVE <input type="checkbox"/> DISCONNECTED IN PLACE <input type="checkbox"/> EXEMPT <input type="checkbox"/> JUNKED <input type="checkbox"/> DISPOSITION UNKNOWN	<input checked="" type="checkbox"/> NEW <input type="checkbox"/> 2ND HAND
-------------------	---	--	---	--

IDENTIFIED BY: * <input checked="" type="checkbox"/> DECAL <input type="checkbox"/> STAMP <input type="checkbox"/> TAG	VARIANCE: * <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	TEXAS SPECIAL: * <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
--	---	--

PHYSICAL ADDRESS <small>(if the physical address has changed a first inspection is required)</small>	OWNER ADDRESS	MAILING ADDRESS
---	---------------	-----------------

NAME * Victoria WLE, LP	NAME Victoria WLE, LP	NAME Victoria WLE, LP
-----------------------------------	---------------------------------	---------------------------------

(Address 1) * 1205 S. Bottom Street	(Address 1) 1205 Bottom St	(Address 1) 1205 Bottom St
---	--------------------------------------	--------------------------------------

(City, State, Zip) * Victoria, TX 77901-9161	(City, State, Zip) Victoria, TX 77901-9161	(City, State, Zip) Victoria, TX 77901-9161
--	--	--

LOCATION PHONE: (361) 489-3719 Alex Benavides	OWNER PHONE: (361) 484-0310	CONTACT NAME: Jason Hixson
--	------------------------------------	-----------------------------------

OBJECT LOCATION: * HRSO LP	BUSINESS EMAIL: jhixson@victoriawlepower.com	CONTACT PHONE: (361) 484-0310
--------------------------------------	---	--------------------------------------

Nature of Business: Utility	BUSINESS EMAIL: jhixson@victoriawlepower.com
------------------------------------	---

MANUFACTURER * Thermal Engineering Int.	NAT'L BOARD # 000584	SERIAL NUMBER 17405-1C	MFGR MODEL #
---	--------------------------------	----------------------------------	--------------

Boiler MAWP *	YEAR BUILT *	INTERVAL *	BLR TYPE *	BLR USE CLASS *	BLR USE *	HEATING SURFACE	CAP (GAL)	MIN SRV	MAX STEAM	ASME STAMP *
150	2003	12	Unfired	Power Boiler	Steam Greater than 15 PSI	623485			64073-LB/HR	S

SAFETY RELIEF VALVE DATA			LOW WATER CUTOFF TYPE		FUEL *	BTU/HR INPUT
SET PRESSURE HIGHEST * 154	TOTAL CAP. * 65622	# OF SAFETIES 3	<input type="checkbox"/> PROBE TYPE	<input type="checkbox"/> FLOAT & CHAMBER	Recovered Heat	BTU/HR OUTPUT
LOWEST * 145	<input type="checkbox"/> BTU/HR	<input checked="" type="checkbox"/> #/HR	<input type="checkbox"/> FLOW SWITCH	<input checked="" type="checkbox"/> OTHER Transmitter		
EXPANSION TANK ASME * <input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> N/A			EXPANSION TANK MAWP 1000		EXTERNAL PIPE ASME <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/> N/A	

EXTENSION INSPECTION? <input type="checkbox"/> YES <input type="checkbox"/> NO	EXTENSION APPROVAL DATE (IF APPLICABLE)
--	---

Comments: Satisfactory internal certificate inspection. No adverse conditions found.

ITEM # - LAW/RULE	VIOLATION (ATTACH ADDITIONAL PAGES IF NECESSARY)

I HEREBY CERTIFY THAT THIS IS A TRUE REPORT AS A RESULT OF MY INSPECTION.

Manuel Del Bosque

SIGNATURE OF INSPECTOR
Manuel Del Bosque

1816
TX COMMISSION #

ARISE Incorporated
INSPECTION ORG.

Shea Watts, Operations Lead Technician (361) 489-3710
SIGNATURE OF INDIVIDUAL PRESENT AT INSPECTION *

03/23/2023
DATE (MM/DD/YY) *

IS CONDITION OF OBJECT SUCH THAT A CERTIFICATE MAY BE ISSUED? * YES NO (IF NO, EXPLAIN FULLY UNDER VIOLATIONS)