



TEXAS DEPARTMENT OF LICENSING & REGULATION

Regulatory Program Management Division • PO Box 12157 • Austin, Texas 78711 • (512) 463-6599

www.tdlr.texas.gov

Boiler Equipment Report of Inspection

PURSUANT TO CHAPTER 755, HEALTH AND SAFETY CODE, 16 TX ADMINISTRATIVE CODE, CHAPTER 65, AND OCCUPATIONS CODE CHAPTER 51

| | | | | | | | | |
|----------|--|--|-----------------------------------|-----------|--|--|---------------------------------|---|
| TX# * | <input type="checkbox"/> 1ST INSPECTION | <input checked="" type="checkbox"/> INTERNAL | <input type="checkbox"/> EXTERNAL | STATUS: * | <input checked="" type="checkbox"/> ACTIVE | <input type="checkbox"/> DISCONNECTED IN PLACE | <input type="checkbox"/> EXEMPT | <input checked="" type="checkbox"/> NEW |
| TX237594 | <input checked="" type="checkbox"/> SUBSEQUENT | <input type="checkbox"/> NON-CERTIFICATE | | | <input type="checkbox"/> JUNKED | <input type="checkbox"/> DISPOSITION UNKNOWN | | <input type="checkbox"/> 2ND HAND |

| | | | | | | | | | |
|------------------|---|--------------------------------|------------------------------|-------------|------------------------------|--|------------------|------------------------------|--|
| IDENTIFIED BY: * | <input checked="" type="checkbox"/> DECAL | <input type="checkbox"/> STAMP | <input type="checkbox"/> TAG | VARIANCE: * | <input type="checkbox"/> YES | <input checked="" type="checkbox"/> NO | TEXAS SPECIAL: * | <input type="checkbox"/> YES | <input checked="" type="checkbox"/> NO |
|------------------|---|--------------------------------|------------------------------|-------------|------------------------------|--|------------------|------------------------------|--|

| | | |
|---|---------------|-----------------|
| PHYSICAL ADDRESS <small>(if the physical address has changed a first inspection is required)</small> | OWNER ADDRESS | MAILING ADDRESS |
|---|---------------|-----------------|

| | | |
|--|--|----------------------------|
| NAME * | NAME | NAME |
| Vistra Energy Corp. "Oak Grove SES" | Vistra Energy Corp. "Oak Grove SES" | Vistra Energy Corp. |

| | | |
|--------------------------|--------------------------|----------------------------|
| (Address 1) * | (Address 1) | (Address 1) |
| 8127 Oak Grove Rd | 8127 Oak Grove Rd | 8127 Oak Grove Road |

| | | |
|--------------------------|--------------------------|---------------------------|
| (City, State, Zip) * | (City, State, Zip) | (City, State, Zip) |
| Bremond, TX 76629 | Bremond, TX 76629 | Franklin, TX 77856 |

| | | |
|-----------------|--------------|---------------------------------------|
| LOCATION PHONE: | OWNER PHONE: | CONTACT NAME: Richard Reistino |
|-----------------|--------------|---------------------------------------|

| | | |
|-------------------------|------------------------------------|--|
| OBJECT LOCATION: * | BUSINESS EMAIL: | CONTACT PHONE: 979-828-6590 |
| Aux. Boiler Area | Nature of Business: Utility | BUSINESS EMAIL: richard.reistino@luminant.com |

| | | | |
|-------------------------|---------------|-----------------|----------------------|
| MANUFACTURER * | NAT'L BOARD # | SERIAL NUMBER | MFGR MODEL # |
| Rentech Blr Serv | 442 | 2006-114 | 2006-14 - 442 |

| Boiler MAWP * | YEAR BUILT * | INTERVAL * | BLR TYPE * | BLR USE CLASS * | BLR USE * | HEATING SURFACE | CAP (GAL) | MIN SRV | MAX STEAM | ASME STAMP * |
|---------------|--------------|------------|------------|-----------------|---------------------------|-----------------|-----------|---------|--------------|--------------|
| 350 | 2007 | 12 | Water Tube | Power Boiler | Steam Greater than 15 PSI | 23971 | | | 250000-LB/HR | S |

| | | | | | | |
|--------------------------|--------------|---------------------------------|--|--|-------------|---------------|
| SAFETY RELIEF VALVE DATA | | | LOW WATER CUTOFF TYPE | | FUEL * | BTU/HR INPUT |
| SET PRESSURE HIGHEST * | TOTAL CAP. * | # OF SAFETIES | <input checked="" type="checkbox"/> PROBE TYPE | <input type="checkbox"/> FLOAT & CHAMBER | Natural Gas | BTU/HR OUTPUT |
| 324 | 279991 | 3 | <input type="checkbox"/> FLOW SWITCH | <input type="checkbox"/> OTHER _____ | | |
| LOWEST * 240 | | <input type="checkbox"/> BTU/HR | <input checked="" type="checkbox"/> #/HR | MAWP: 350 | | 250000000 |

| | | |
|--|---------------------|---|
| EXPANSION TANK ASME * <input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> N/A | EXPANSION TANK MAWP | EXTERNAL PIPE ASME <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/> N/A |
|--|---------------------|---|

| | |
|--|---|
| EXTENSION INSPECTION? <input type="checkbox"/> YES <input type="checkbox"/> NO | EXTENSION APPROVAL DATE (IF APPLICABLE) |
|--|---|

Comments: During my visit, I internally and externally inspected the boiler for any signs of leakage or overheating. The boiler and foundation appeared to be in good condition. I reviewed the SRV(s), low water cut-off, pressure gage, sight glass, and all other associated items. No recommendations were made as a result of this inspection.

| ITEM # - LAW/RULE | VIOLATION (ATTACH ADDITIONAL PAGES IF NECESSARY) |
|-------------------|--|
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |

I HEREBY CERTIFY THAT THIS IS A TRUE REPORT AS A RESULT OF MY INSPECTION.

| | | |
|--|-------------------------|------------------------------|
| _____ SIGNATURE OF INSPECTOR Derrick Lindemann | 1884 TX COMMISSION # | FM Global INSPECTION ORG. |
|--|-------------------------|------------------------------|

| | |
|--|---------------------------------|
| Richard Reistino - Engineering _____ SIGNATURE OF INDIVIDUAL PRESENT AT INSPECTION * | 04/14/2021 DATE (MM/DD/YY) * |
|--|---------------------------------|

IS CONDITION OF OBJECT SUCH THAT A CERTIFICATE MAY BE ISSUED? * YES NO (IF NO, EXPLAIN FULLY UNDER VIOLATIONS)