



TEXAS DEPARTMENT OF LICENSING & REGULATION

P.O. Box 12157 • Austin, Texas 78711-2157

(512) 539-5716 • www.tdlr.texas.gov • boilers@tdlr.texas.gov

Boiler Equipment Report of Inspection

PURSUANT TO CHAPTER 755, HEALTH AND SAFETY CODE, 16 TX ADMINISTRATIVE CODE, CHAPTER 65, AND OCCUPATIONS CODE CHAPTER 51

TX# *	<input type="checkbox"/> 1ST INSPECTION	<input checked="" type="checkbox"/> INTERNAL	<input type="checkbox"/> EXTERNAL	STATUS: *	<input checked="" type="checkbox"/> ACTIVE	<input type="checkbox"/> DISCONNECTED IN PLACE	<input type="checkbox"/> EXEMPT	<input checked="" type="checkbox"/> NEW
TX192095	<input checked="" type="checkbox"/> SUBSEQUENT	<input type="checkbox"/> NON-CERTIFICATE			<input type="checkbox"/> JUNKED	<input type="checkbox"/> DISPOSITION UNKNOWN		<input type="checkbox"/> 2ND HAND

IDENTIFIED BY: *	<input type="checkbox"/> DECAL	<input checked="" type="checkbox"/> STAMP	<input type="checkbox"/> TAG	VARIANCE: *	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	TEXAS SPECIAL: *	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
------------------	--------------------------------	---	------------------------------	-------------	------------------------------	--	------------------	------------------------------	--

PHYSICAL ADDRESS <small>(if the physical address has changed a first inspection is required)</small>	OWNER ADDRESS	MAILING ADDRESS
---	---------------	-----------------

NAME *	NAME	NAME
Calpine Corporation-Bosque Energy Center	Calpine Corporation-Bosque Energy Center	Calpine Corporation-Bosque Energy Center

(Address 1) *	(Address 1)	(Address 1)
557 County Road 3610	557 County Road 3610	557 County Road 3610

(City, State, Zip) *	(City, State, Zip)	(City, State, Zip)
Clifton, TX 76634-3607	Clifton, TX 76634-3607	Clifton, TX 76634-3607

LOCATION PHONE: 254 622-2110	OWNER PHONE:	CONTACT NAME: Jeremiah Gipson
------------------------------	--------------	-------------------------------

OBJECT LOCATION: *	BUSINESS EMAIL:	CONTACT PHONE: 254-622-8515
Unit 3	Nature of Business: Utility	BUSINESS EMAIL: Jeremiah.Gipson@calpine.com

MANUFACTURER *	NAT'L BOARD #	SERIAL NUMBER	MFGR MODEL #
Alstom	024151	66008400	

Boiler MAWP *	YEAR BUILT *	INTERVAL *	BLR TYPE *	BLR USE CLASS *	BLR USE *	HEATING SURFACE	CAP (GAL)	MIN SRV	MAX STEAM	ASME STAMP *
2125	2000	12	Fire/Water Tube	Power Boiler	Steam Greater than 15 PSI	1627334			399000-LB/HR	S

SAFETY RELIEF VALVE DATA	LOW WATER CUTOFF TYPE	FUEL *	BTU/HR INPUT
--------------------------	-----------------------	--------	--------------

SET PRESSURE HIGHEST *	TOTAL CAP. *	# OF SAFETIES	<input type="checkbox"/> PROBE TYPE	<input type="checkbox"/> FLOAT & CHAMBER	Recovered Heat	BTU/HR OUTPUT
2189	652114	2	<input type="checkbox"/> FLOW SWITCH	<input checked="" type="checkbox"/> OTHER Transmitter		
LOWEST * 2125		<input type="checkbox"/> BTU/HR	<input checked="" type="checkbox"/> #/HR	MAWP: 3000		

EXPANSION TANK ASME * <input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> N/A	EXPANSION TANK MAWP	EXTERNAL PIPE ASME <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/> N/A
--	---------------------	---

EXTENSION INSPECTION? <input type="checkbox"/> YES <input type="checkbox"/> NO	EXTENSION APPROVAL DATE (IF APPLICABLE)
--	---

Comments: No violations noted at this time. Internal inspection revealed no defects or noticeable out of tolerance conditions. There was some "work in progress on the drain line in the form of a modification to prevent overheating. Minor HP evac tube flex observed.

ITEM # - LAW/RULE	VIOLATION (ATTACH ADDITIONAL PAGES IF NECESSARY)
-------------------	--

ITEM # - LAW/RULE	VIOLATION (ATTACH ADDITIONAL PAGES IF NECESSARY)
-------------------	--

ITEM # - LAW/RULE	VIOLATION (ATTACH ADDITIONAL PAGES IF NECESSARY)
-------------------	--

ITEM # - LAW/RULE	VIOLATION (ATTACH ADDITIONAL PAGES IF NECESSARY)
-------------------	--

ITEM # - LAW/RULE	VIOLATION (ATTACH ADDITIONAL PAGES IF NECESSARY)
-------------------	--

ITEM # - LAW/RULE	VIOLATION (ATTACH ADDITIONAL PAGES IF NECESSARY)
-------------------	--

ITEM # - LAW/RULE	VIOLATION (ATTACH ADDITIONAL PAGES IF NECESSARY)
-------------------	--

ITEM # - LAW/RULE	VIOLATION (ATTACH ADDITIONAL PAGES IF NECESSARY)
-------------------	--

ITEM # - LAW/RULE	VIOLATION (ATTACH ADDITIONAL PAGES IF NECESSARY)
-------------------	--

ITEM # - LAW/RULE	VIOLATION (ATTACH ADDITIONAL PAGES IF NECESSARY)
-------------------	--

ITEM # - LAW/RULE	VIOLATION (ATTACH ADDITIONAL PAGES IF NECESSARY)
-------------------	--

ITEM # - LAW/RULE	VIOLATION (ATTACH ADDITIONAL PAGES IF NECESSARY)
-------------------	--

ITEM # - LAW/RULE	VIOLATION (ATTACH ADDITIONAL PAGES IF NECESSARY)
-------------------	--

ITEM # - LAW/RULE	VIOLATION (ATTACH ADDITIONAL PAGES IF NECESSARY)
-------------------	--

ITEM # - LAW/RULE	VIOLATION (ATTACH ADDITIONAL PAGES IF NECESSARY)
-------------------	--

I HEREBY CERTIFY THAT THIS IS A TRUE REPORT AS A RESULT OF MY INSPECTION.

Timothy Larrew
SIGNATURE OF INSPECTOR
Timothy Larrew

1831
TX COMMISSION #

ARISE Incorporated
INSPECTION ORG.

Jeremiah Gipson, 254 722-2956
SIGNATURE OF INDIVIDUAL PRESENT AT INSPECTION *

03/31/2025
DATE (MM/DD/YY) *

IS CONDITION OF OBJECT SUCH THAT A CERTIFICATE MAY BE ISSUED? *	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	(IF NO, EXPLAIN FULLY UNDER VIOLATIONS)
---	---	---