



ELBI Number: 5573

# Texas Department of Licensing and Regulation

*Licensing Division*

*P.O. Box 12157 - Austin, Texas 78711-2157 - (512) 463-6599 - (800) 803-9202 - fax (512) 475-2871*

*Web site: [www.tdlr.texas.gov](http://www.tdlr.texas.gov)*

JANUARY 29 2024

VICTOR ARMENDARIZ  
CLAYDESTA BUILDINGS LP  
6 DESTA DR STE 5725  
MIDLAND TX 79705-5606

ELBI Number: 5573  
Equipment Number: 87545

Date of Inspection: 12/07/23

Re: Request For Information for Certificate of Compliance for an Elevator, Escalator, or Related Equipment for CLAYDESTA CENTER

The Department received the Elevator Equipment Report of Inspection referenced above on JANUARY 26 2024. However, the report is incomplete.

The following information is required to continue processing the report:

- \* Your payment was insufficient. The fee to process an inspection report and receive a certificate of compliance is \$20. If the report is not submitted within 60 days of the date of inspection, late fees will be charged. Late fees are \$10 for every 30-day period after the 60 days. The amount required to continue processing your report is  
\$ 20.00.

You must return a copy of this letter with any requested information. You can submit required attachments via TDLR webform at <https://www.tdlr.texas.gov/help>. You may also contact Customer Service for assistance at 512-463-6599 or 800-803-9202.

Thank you,

Licensing Division