



# TEXAS DEPARTMENT OF LICENSING AND REGULATION

Licensing Division

P. O. Box 12157 • Austin, Texas 78711 • (512) 463-6599 • (800) 803-9202

Fax: (512) 475-2871 • Web site: [www.tdlr.texas.gov](http://www.tdlr.texas.gov)

## NOTICE OF OVERDUE ANNUAL INSPECTION

GREG WHITNER  
BANK OF AMERICA  
7105 CORPORATE DR  
PLANO TX 75024-4100

Letter Date: 10/28/2024

ELBI #: 18943

Equipment Decal #: 25062

Date of Last Inspection: 10/19/2023

Date Inspection Due: 10/19/2024

**Equipment Location:**

BANK OF AMERICA  
BANK OF AMERICA BUILDING C  
7105 CORPORATE DRIVE  
PLANO TX 75024

The Texas Department of Licensing and Regulation (TDLR) has **not** received notification that the required annual inspection has been completed. The elevator, escalator, or related equipment referenced above must be inspected as required by Texas Health & Safety Code § 754.019. Failure to have an annual inspection may subject the building owner to administrative penalties of up to \$5,000 per day for each violation in accordance with Chapter 51, Texas Occupations Code. If the referenced equipment has been inspected, please ask your elevator inspector to notify TDLR that the inspection has been completed.

The information below will guide you in scheduling your inspection.

**1. How do I schedule an inspection?**

Contact your elevator inspector to schedule an inspection. You may go online at [www.tdlr.texas.gov/LicenseSearch](http://www.tdlr.texas.gov/LicenseSearch) to find an Elevator Inspector registered with the Texas Department of Licensing and Regulation (TDLR).

**2. When do I get a copy of the *Elevator Equipment Report of Inspection* (“Inspection Report”)?**

Your elevator inspector has five days from the inspection date to provide you with a copy of the Inspection Report.

**3. Who is responsible for obtaining and filing the Inspection Report with filing fees?**

The building owner is responsible for obtaining the Inspection Report from the elevator inspector and for filing the Inspection Report and filing fees with TDLR. The owner or owner’s agent must:

- Verify all information on the Inspection Report regarding the owner, the building, and the building contact is completed and correct.
- Sign and date the Inspection Report with the current date.
- Mail the Inspection Report and filing fees (\$20 per piece of equipment) to TDLR not later than 30 days after the date of the inspection.
- Display the Certificate of Compliance you receive from TDLR after filing your Inspection Report and filing fees.

**4. What if the information on my inspection report is incomplete or wrong?**

Contact your elevator inspector to complete or make any corrections to the Inspection Report. File the corrected Inspection Report and filing fees with TDLR.

**If you need further assistance or have any questions, please contact TDLR.**