



ELBI Number: 5573

Texas Department of Licensing and Regulation

Licensing Division

P.O. Box 12157 - Austin, Texas 78711-2157 - (512) 463-6599 - (800) 803-9202 - fax (512) 475-2871

Web site: www.tdlr.texas.gov

JUNE 26 2025

VICTOR ARMENDARIZ
6 DESTA DR STE 5725
MIDLAND TX 79705-5606

ELBI Number: 5573
Equipment Number: 106171

Date of Inspection: 05/28/25

Re: Request For Information for Certificate of Compliance for an Elevator, Escalator, or Related Equipment for CLAYDESTA CENTER

The Department received the Elevator Equipment Report of Inspection referenced above on JUNE 16 2025. However, the report is incomplete.

The following information is required to continue processing the report:

- * Please contact the inspector to indicate type of unit inspected.
- * Owner phone number

You must return a copy of this letter with any requested information. You can submit required attachments via TDLR webform at <https://www.tdlr.texas.gov/help>. You may also contact Customer Service for assistance at 512-463-6599 or 800-803-9202.

Thank you,

Licensing Division